	Берги 124												क्षा कारता मु व
	DATE			7.	O P S						9		**************************************
									1 2		10		·
				- Proprietable	CONTROL SENSON	PSINDANO INVESTOR		ofide reconstruction and			12		*******
							-		== 5		13		
25X1A	TO	DIRECTOR							0		14		
25A IA .	25.04								7		15	······································	******
	FROM										16		
	ACTION: OPS 1-8							ı	IMMEDIATE				
	INFO	¢											
	♥/PMAssassastate	TOR 1731Z 14	NOV 63							25X1A	IN	50398	
25X1A	70	IMMEDIATE	33 St. Carlot Carlot Control Carlot C	MFO			ter, established bearing	er Barther to an annual an		CITE		052 9	
25X1A													

FOR COL LEDFORD FROM

1. MSN 3239 PRESENTED NO PROBLEM EXCEPT THE WX WAS WORSE THAN BRIEFED. THE PILOT OBSERVED IMPROVEMENT IN THE WX ON THE FIRST FLIGHT LINE APPROX ONE HOUR AFTER THE TRACK WAS COVERED WHICH INDICATES A GRADUAL BURN OFF OF LOW STRATUS WITH INCREASED SUN ANGLE.

25X1A

25X1A

- 2. THIS WAS THE FIRST SORTIE FLOWN BY ON THIS EXERCISE AND HE HAD NO PROBLEM IN MAINTAINING TRACK IN AREAS WHERE HE WAS ABLE TO MAINTAIN VISUAL REFERENCE TO THE GROUND.
- J. EQUIPMENT OPERATION WAS SATISFACTORY FOR ALL SYSTEMS AND THERE WERE NO KNOWN MALFUNCTIONS. POST FLIGHT CHECKS INDICATES HEAVY RADAR ACTIVITY PICKED UP BY SYSTEM 6.

Approved For Release 2000/06/01 : CIA-RDP89B00569B000700190034-1

4. THE ARTICLE LANDED WITH AN OK FLIGHT AND WE'RE READY FOR MEN 3240

25X1A

25X1A

25X1A

THE ROUTE FOR MSN 3239 WAS NOT RECEIVED UNTIL 1700L.

THIS PRESENTED A MINOR PROBLEM IN SELECTION OF MATERIALS

TO BE USED ON THE SORTIE. WE WENT AHEAD AND LOADED 6,000 FT.

ROLLS WHEREAS 4,000 FT WOULD HAVE BEEN QUITE ADEQUATE. EARLIER

RECEIPT OF ROUTE WOULD HAVE ALSO FACILITATED CORRECTION OF ERROR

IN THAI BORDER CROSSING AND LANDING TIME IN 6385)

WHICH WAS AMENDED BY 6401.

END OF MESSAGE